

DATED	LAB S.No.	RECEIVED FROM	DAILY S.No.	333	SODIUM THIOSULPHATE	FINAL REPORT (AFTER 72 HOURS)	FINAL REPORTING DATE	RESULT
28/04/2020	2171	Samples received from A.E. , SJPN Ltd.	1	KASUMPTI RESERVOIR	added	thermotolerant E.coli not detected	05-01-20	Satisfactory
	2172		2	SAKRALA TANK	added		05-01-20	Excellent
	2173		3	Phase III Tank No.1	added	thermotolerant E.coli not detected	05-01-20	Satisfactory
	2174		4	TARA MATA MANDIR TANK	added	thermotolerant E.coli not detected	05-01-20	Satisfactory
	2175		5	SDA KASUMPTI TANK	added		05-01-20	Excellent
	2176		6	Public tap near Apna Medical store Chotta Shimla	added	thermotolerant E.coli not detected	05-01-20	Satisfactory
	2177		7	PUBLIC TAP NEAR POLICE GOMATI CHOTTA SHIMLA	added	thermotolerant E.coli not detected	05-01-20	Satisfactory
	2178		8	PUBLIC TAP NEAR SERVANT QUARTERS KNOLLS WOOD	added		05-01-20	Excellent
	2179		9	MAINSFIELD TANK	added		05-01-20	Excellent
	2180		10	Jakhu tank No. I	added	thermotolerant E.coli not detected	05-01-20	Satisfactory
	2181		11	BHIMAKALI TANK	added		05-01-20	Excellent
	2182		12	Tutikandi tank	added	thermotolerant E.coli not detected	05-01-20	Satisfactory
	2183		13	Ridge tank outlet	added		05-01-20	Excellent
	2184		14	BHARARI TANK	added		05-01-20	Excellent

	2185		15	Gumma inlet	added	thermotolerant E.coli not detected	05-01-20	Satisfactory
	2186		16	Giri inlet	added		05-01-20	Excellent
	2187		17	SANJAULI RESERVOIR	added	thermotolerant E.coli not detected	05-01-20	Satisfactory
	2188		18	Dhali Catchment	added		05-01-20	Excellent
	2189		19	CHURAT JAGRATI INLET	added		05-01-20	Excellent
	2190		20	DHALI TANK OUTLET	added		05-01-20	Excellent
29/4/2020	2191	Samples received from A.E. , SJPN Ltd.	1	KASUMPATI RESERVOIR	added	thermotolerant E.coli not detected	05-02-20	Suspicious
	2192		2	PHASE III TANK NO 1	added	thermotolerant E.coli not detected	05-02-20	Suspicious
	2193		3	TARA MATA MANDIR TANK	added	thermotolerant E.coli not detected	05-02-20	Suspicious
	2194		4	PUBLIC TAP NEAR MC OFFICE NEW SHIMLA	added		05-02-20	Excellent
	2195		5	SECTOR 3 OLD TANK OUTLET	added	thermotolerant E.coli not detected	05-02-20	Suspicious
	2196		6	PUBLIC TAP NEAR KRANTI CHOWK	added	thermotolerant E.coli not detected	05-02-20	Satisfactory
	2197		7	SECTOR 3 NEW TANK	added	thermotolerant E.coli not detected	05-02-20	Suspicious

	2198		8	PUBLIC TAP NEAR MANGALA BHAWAN NEW SHIMLA	added	thermotolera nt E.coli not detected	05-02-20	Satisfactory
	2199		9	MAINSFIELD TANK	added	thermotolera nt E.coli not detected	05-02-20	satisfactory
	2200		10	JAKHU TANK NO 1	added	thermotolera nt E.coli not detected	05-02-20	Suspicious
	2201		11	RIDGE TANK OUTLET	added	thermotolera nt E.coli not detected	05-02-20	Suspicious
	2202		12	DHALLI CATCHMENT INLET	added	thermotolera nt E.coli not detected	05-02-20	satisfactory
	2203		13	CHURAT AND JAGRITI	added		05-02-20	Excellent
	2204		14	DHALLI TANK OUTLET	added	thermotolera nt E.coli not detected	05-02-20	Suspicious
	2205		15	GUMMA INLET	added		05-02-20	Excellent
	2206		16	GIRI INLET	added	thermotolera nt E.coli not detected	05-02-20	satisfactory
	2207		17	SANJAULI RESERVOIR	added	thermotolera nt E.coli not detected	05-02-20	satisfactory
	2208		18	KLESTON TANK	added	thermotolera nt E.coli not detected	05-02-20	satisfactory
	2209		19	ADVANCE STUDY TANK	added		05-02-20	Excellent

	2210		20	PHAGLI TANK	added	thermotolera nt E.coli not detected	05-02-20	satisfactory
30/04/2020	2211	Samples received from A.E. , SJPN Ltd.	1	KASUMPTI RESERVOIR	added		05-03-20	Excellent
	2212		2	Phase III tank NO. 1	added		05-03-20	Excellent
	2213		3	TARA MATA MANDIR TANK	added	thermotolera nt E.coli not detected	05-03-20	Unsatisfactory
	2214		4	Jakhu tank No. 1	added		05-03-20	Excellent
	2215		5	RIDGE TANK OUTLET	added		05-03-20	Excellent
	2216		6	MAINSFIELD TANK	added	thermotolera nt E.coli not detected	05-03-20	Satisfactory
	2217		7	PUBLIC TAP NEAR POLICE COLONY BHARARI	added	thermotolera nt E.coli not detected	05-03-20	satisfactory
	2218		8	SUPPLY NEAR BHALLA NIWAS BHARARI	added		05-03-20	Excellent
	2219		9	PUBLIC TAP NEAR BHARARI TEMPLE	added		05-03-20	Excellent
	2220		10	PUBLIC TAP NEAR POLICE GROUND BHARARI	added		05-03-20	Excellent
	2221		11	BHARARI TANK	added	thermotolera nt E.coli not detected	05-03-20	satisfactory
	2222		12	KLESTAN TANK	added		05-03-20	Excellent
	2223		13	CHAKKAR TANK	added		05-03-20	Excellent
	2224		14	103 Tank	added		05-03-20	Excellent
	2225		15	Dhali Catchment	added		05-03-20	Excellent
	2226		16	CHURAT JAGRATI INLET	added	thermotolera nt E.coli not detected	05-03-20	satisfactory
	2227		17	DHALI TANK OUTLET	added		05-03-20	Excellent

	2228		18	SANJAULI RESERVOIR	added		05-03-20	Excellent
	2229		19	Gumma inlet	added		05-03-20	Excellent
	2230		20	Giri inlet	added		05-03-20	Excellent
05-01-20	2231	Samples received from A.E. , SJPN Ltd.	1	KASUMPATI RESERVOIR	added		05-04-20	Excellent
	2232		2	PHASE III TANK NO 1	added		05-04-20	Excellent
	2233		3	TARA MATA MANDIR TANK	added		05-04-20	Excellent
	2234		4	MAINSFIELD TANK	added		05-04-20	Excellent
	2235		5	JAKHU TANK NO 1	added		05-04-20	Excellent
	2236		6	PUBLIC TAP NEAR SIRJI LINE	added		05-04-20	Excellent
	2237		7	PUBLIC TAP NEAR EVA SALES CORPORATION GANJ BAZAR	added		05-04-20	Excellent
	2238		8	PUBLIC TAP NEAR PURUSHARTHI BASTI	added		05-04-20	Excellent
	2239		9	PUBLIC TAP NEAR KHADI BANDHAR MALL ROAD	added	thermotolerant E.coli not detected	05-04-20	Unsatisfactory
	2240		10	PUBLIC TAP NEAR HPMC RIDGE	added		05-04-20	Excellent
	2241		11	RIDGE TANK OUTLET	added		05-04-20	Excellent
	2242		12	BHIMAKALI TANK	added	thermotolerant E.coli not detected	05-04-20	satisfactory
	2243		13	TUTIKANDHI TANK	added	thermotolerant E.coli not detected	05-04-20	Satisfactory
	2244		14	BHARARI TANK	added		05-04-20	Excellent
	2245		15	DHALI TANK OUTLET	added		05-04-20	Excellent
	2246		16	CHURAT AND JAGRITI	added	thermotolerant E.coli not detected	05-04-20	satisfactory
	2247		17	DHALI CATCHMENT	added	thermotolerant E.coli not detected	05-04-20	Unsatisfactory
	2248		18	GUMMA INLET	added		05-04-20	Excellent

	2249		19	GIRI INLET	added	thermotolerant E.coli not detected	05-04-20	Suspicious
	2250		20	SANJAULI RESERVOIR	added		05-04-20	Excellent
05-02-20	2251	Samples received from A.E. , SJPN Ltd.	1	KASUMPTI RESERVOIR	added	thermotolerant E.coli not detected	05-05-20	satisfactory
	2252		2	Phase III Tank No. I	added		05-05-20	Excellent
	2253		3	TARA MATA MANDIR TANK	added		05-05-20	Excellent
	2254		4	Public tap near Apna Medical store Chotta Shimla	added		05-05-20	Excellent
	2255		5	Public tap near Police gumati	added		05-05-20	Excellent
	2256		6	MAINSFIELD TANK	added		05-05-20	excellent
	2257		7	Jakhu Tank No. I	added	thermotolerant E.coli not detected	05-05-20	satisfactory
	2258		8	Ridge tank outlet	added		05-05-20	Excellent
	2259		9	SUMMER HILL BAJAR TANK	added	thermotolerant E.coli not detected	05-05-20	Unsatisfactory
	2260		10	Public tap near Lower Summer Hill	added	thermotolerant E.coli not detected	05-05-20	Unsatisfactory
	2261		11	Public tap near Summer hill Chowk	added	thermotolerant E.coli not detected	05-05-20	Unsatisfactory
	2262		12	ADVANCE STUDY TANK	added		05-05-20	Excellent
	2263		13	KLESTAN TANK	added		05-05-20	Excellent
	2264		14	PHAGLI TANK	added		05-05-20	Excellent
	2265		15	Dhali catchment	added		05-05-20	Excellent
	2266		16	CHURAT JAGRATI INLET	added		05-05-20	Excellent
	2267		17	DHALI TANK OUTLET	added		05-05-20	excellent

	2268		18	Gumma Inlet	added	thermotolera nt E.coli not detected	05-05-20	Unsatisfactory
	2269		19	Giri inlet	added	thermotolera nt E.coli not detected	05-05-20	Suspicious
	2270		20	SANJAULI RESERVOIR	added		05-05-20	Excellent
05-03-20	2271	Samples received from A.E. , SJPN Ltd.	1	KASUMPATI RESERVOIR	added		05-06-20	Excellent
	2272		2	PHASE III TANK NO 1	added		05-06-20	Excellent
	2273		3	TARA MATA MANDIR TANK	added		05-06-20	Excellent
	2274		4	SECTOR 3 OLD TANK OUTLET(REPEAT)	added		05-06-20	Excellent
	2275		5	PUBLIC TAP NEAR KRANTI CHOWK(REPEAT)	added		05-06-20	Excellent
	2276		6	SECTOR 3 NEW TANK(REPEAT)	added		05-06-20	Excellent
	2277		7	PUBLIC TAP NEAR MANGLA BHAWAN(REPEAT)	added		05-06-20	Excellent
	2278		8	MAINSFIELD TANK	added		05-06-20	Excellent
	2279		9	JAKHU TANK NO 1	added		05-06-20	Excellent
	2280		10	RIDGE TANK OUTLET	added		05-06-20	Excellent
	2281		11	CHAKKER TANK	added		05-06-20	Excellent
	2282		12	103 TANK	added		05-06-20	Excellent
	2283		13	BHARARI TANK	added		05-06-20	Excellent
	2284		14	GUMMA INLET	added		05-06-20	Excellent
	2285		15	GIRI INLET	added	thermotolera nt E.coli not detected	05-06-20	Satisfactory
	2286		16	SANJAULI RESERVOIR	added	thermotolera nt E.coli not detected	05-06-20	Satisfactory
	2287		17	DHALLI CATCHMENT INLET	added		05-06-20	Excellent
	2288		18	CHURAT AND JAGRITI INLET	added		05-06-20	Excellent
	2289		19	DHALLI TANK OUTLET	added		05-06-20	Excellent
	2290		20	KALYANI TANK CHARABRA	added		05-06-20	Excellent

05-04-20	2291	Samples received from A.E. , SJPN Ltd.	1	KASUMPTI RESERVOIR	added		05-07-20	Excellent
	2292		2	Phase III tank No. 1	added		05-07-20	Excellent
	2293		3	TARA MATA MANDIR TANK	added	thermotolera nt E.coli not detected	05-07-20	Satisfactory
	2294		4	Jakhu tank near Ropeway	added		05-07-20	Excellent
	2295		5	MAINSFIELD TANK	added	thermotolera nt E.coli not detected	05-07-20	Satisfactory
	2296		6	BHIMAKALI TANK	added	thermotolera nt E.coli not detected	05-07-20	Satisfactory
	2297		7	Public tap near Vaidya niwas Totu	added		05-07-20	Excellent
	2298		8	Public tap near Gupta pan House Totu	added	thermotolera nt E.coli not detected	05-07-20	Satisfactory
	2299		9	Public tap near Totu chowk	added	thermotolera nt E.coli not detected	05-07-20	satisfactory
	2300		10	Public tap near Sheru dhaba Yadgar Totu	added		05-07-20	Excellent
	2301		11	YADGAR TANK	added	thermotolera nt E.coli not detected	05-07-20	satisfactory
	2302		12	Tutikandi tank	added		05-07-20	Excellent
	2303		13	RIDGE TANK OUTLET	added	thermotolera nt E.coli not detected	05-07-20	Suspicious

	2304		14	KLESTAN TANK	added	thermotolerant E.coli not detected	05-07-20	Suspicious
	2305		15	Gumma inlet	added	thermotolerant E.coli not detected	05-07-20	satisfactory
	2306		16	Giri inlet	added	thermotolerant E.coli not detected	05-07-20	satisfactory
	2307		17	SANJAULI RESERVOIR	added		05-07-20	Excellent
	2308		18	Dhali catchment	added	thermotolerant E.coli not detected	05-07-20	Suspicious
	2309		19	CHURAT JAGRATI INLET	added	thermotolerant E.coli not detected	05-07-20	satisfactory
	2310		20	DHALI TANK OUTLET	added		05-07-20	Excellent
05-05-20	2311	Samples received from A.E. , SJPN Ltd.	1	KASUMPTI RESERVOIR	added		05-08-20	Excellent
	2312		2	MAINSFIELD TANK	added		05-08-20	Excellent
	2313		3	Jakhu tank near Ropeway	added		05-08-20	Excellent
	2314		4	Gumma inlet	added		05-08-20	Excellent
	2315		5	Giri inlet	added		05-08-20	Excellent
	2316		6	SANJAULI RESERVOIR	added		05-08-20	Excellent
	2317		7	NORTH OAK UG TANK	added		05-08-20	Excellent
	2318		8	NORTH OAK OH TANK	added		05-08-20	Excellent
	2319		9	PUBLIC TAP NEAR OLD POLICE THANA SANJAULI	added		05-08-20	Excellent
	2320		10	Public tap near Laxmi narayan temple	added		05-08-20	Excellent
	2321		11	Public tap near Goel Apartment Dhingu	added		05-08-20	Excellent
	2322		12	DHINGU MANDIR TANK	added		05-08-20	Excellent
	2323		13	Dhalli catchment inlet	added		05-08-20	Excellent
	2324		14	CHURAT JAGRATI INLET	added		05-08-20	Excellent

	2325		15	DHALI TANK OUTLET	added		05-08-20	Excellent
	2326		16	ADVANCE STUDY TANK	added		05-08-20	Satisfactory
	2327		17	Summer hill chowk tank	added		05-08-20	Excellent
	2328		18	PHAGLI TANK	added		05-08-20	Excellent
	2329		19	Public tap near Khaddi(repeat)	added		05-08-20	Excellent
	2330		20	RIDGE TANK OUTLET	added		05-08-20	Excellent
05-06-20	2331	Samples received from A.E. , SJPN Ltd.	1	KASUMPATI RESERVOIR	added		05-09-20	Excellent
	2332		2	PHASE III TANK NO 1	added		05-09-20	Excellent
	2333		3	TARA MATA MANDIR TANK	added		05-09-20	Excellent
	2334		4	PUBLIC TAP NEAR PANCHIATHA	added		05-09-20	Excellent
	2335		5	PUBLIC TAP NEAR BYPASS ROAD KHALINI	added		05-09-20	Excellent
	2336		6	PUBLIC TAP NEAR KHALINI CHOWK	added		05-09-20	Excellent
	2337		7	MAINSFIELD TANK	added		05-09-20	Excellent
	2338		8	JAKHU TANK NEAR ROPEWAY	added		05-09-20	Excellent
	2339		9	RIDGE TANK OUTLET(REPEAT)	added	thermotolerant E.coli not detected	05-09-20	Satisfactory
	2340		10	PUBLIC TAP NEAR SUMMER HILL CHOWK	added		05-09-20	Excellent
	2341		11	PUBLIC TAP NEAR LOWER SUMMER HILL (REPEAT)	added	thermotolerant E.coli not detected	05-09-20	Satisfactory
	2342		12	CHAKKAR TANK	added	thermotolerant E.coli not detected	05-09-20	Satisfactory
	2343		13	103 TANK	added	thermotolerant E.coli not detected	05-09-20	Satisfactory
	2344		14	BHARARI TANK	added	thermotolerant E.coli not detected	05-09-20	Satisfactory

	2345		15	DHALLI CATCHMENT	added		05-09-20	Excellent
	2346		16	CHURAT AND JAGRITI INLET	added	thermotolera nt E.coli not detected	05-09-20	Suspicious
	2347		17	DHALLI TANK OUTLET	added	thermotolera nt E.coli not detected	05-09-20	Unsatisfactory
	2348		18	SANJAULI RESERVOIR	added	thermotolera nt E.coli not detected	05-09-20	Satisfactory
	2349		19	GIRI INLET	added	thermotolera nt E.coli not detected	05-09-20	Satisfactory
	2350		20	GUMMA INLET	added		05-09-20	Excellent
05-07-20	2351	Samples received from A.E. , SJPN Ltd.	1	KASUMPTI RESERVOIR	added		05-10-20	Excellent
	2352		2	PUBLIC TAP NEAR MC OFFICE NEW SHIMLA	added		05-10-20	Excellent
	2353		3	Sector-4 Tank New Shimla	added		05-10-20	Excellent
	2354		4	Sector-2 Tank New Shimla	added		05-10-20	Excellent
	2355		5	Sector-1 Tank New Shimla	added		05-10-20	Excellent
	2356		6	TARA MATA MANDIR TANK	added		05-10-20	Excellent
	2357		7	Phase III tank No. 1	added		05-10-20	Excellent
	2358		8	Phase III tank No. 3	added		05-10-20	Excellent
	2359		9	MAINSFIELD TANK	added		05-10-20	Excellent
	2360		10	Jakhu tank near Ropeway	added		05-10-20	Excellent
	2361		11	BHIMAKALI TANK	added	thermotolera nt E.coli not detected	05-10-20	Satisfactory
	2362		12	Tutikandi Tank	added	thermotolera nt E.coli not detected	05-10-20	Suspicious
	2363		13	Ridge tank outlet	added		05-10-20	Excellent
	2364		14	KLESTAN TANK	added		05-10-20	Excellent

	2365		15	GuMMA INLET	added		05-10-20	Excellent
	2366		16	Giri inlet	added		05-10-20	Excellent
	2367		17	SANJAULI RESERVOIR	added	thermotolerant E.coli not detected	05-10-20	Unsatisfactory
	2368		18	DHALI CATCHMENT INLET	added		05-10-20	Excellent
	2369		19	CHURAT JAGRATI INLET	added		05-10-20	Excellent
	2370		20	Dhalli tank outlet	added	thermotolerant E.coli not detected	05-10-20	satisfactory
05-08-20	2371	Samples received from A.E. , SJPN Ltd.	1	KASUMPTI RESERVOIR	added		05-11-20	Excellent
	2372		2	Phase III tank No. 1	added		05-11-20	Excellent
	2373		3	TARA MATA MANDIR TANK	added		05-11-20	Excellent
	2374		4	Public tap near Five bench Jakhu	added		05-11-20	Excellent
	2375		5	Public tap near Dhaulpur house	added		05-11-20	Excellent
	2376		6	Jakhu Tank near ropeway	added		05-11-20	Excellent
	2377		7	Jakhu Tank near Hanuman Temple	added	thermotolerant E.coli not detected	05-11-20	Unsatisfactory
	2378		8	Public tap near Charlie mount	added		05-11-20	Excellent
	2379		9	SUPPLY NEAR HOLLY LODGE	added		05-11-20	Excellent
	2380		10	Ridge tank outlet	added		05-11-20	Excellent
	2381		11	MAINSFIELD TANK	added		05-11-20	Excellent
	2382		12	CHAKKER TANK	added		05-11-20	Excellent
	2383		13	PHAGLI TANK	added	thermotolerant E.coli not detected	05-11-20	Satisfactory
	2384		14	BHARARI TANK	added	thermotolerant E.coli not detected	05-11-20	Unsatisfactory
	2385		15	GuMMA INLET	added		05-11-20	Excellent

	2386		16	Giri inlet	added	thermotolerant E.coli not detected	05-11-20	Satisfactory
	2387		17	SANJAULI RESERVOIR	added		05-11-20	Excellent
	2388		18	DHALI CATCHMENT INLET	added	thermotolerant E.coli not detected	05-11-20	Satisfactory
	2389		19	CHURAT JAGRATI INLET	added		05-11-20	Excellent
	2390		20	Dhali tank outlet	added		05-11-20	Excellent
05-09-20	2391	Samples received from A.E. , SJPN Ltd.	1	KASUMPTI RESERVOIR	added		05-12-20	Excellent
	2392		2	Phase III tank No. 1	added		05-12-20	Excellent
	2393		3	TARA MATA MANDIR TANK	added		05-12-20	Excellent
	2394		4	MAINSFIELD TANK	added		05-12-20	Excellent
	2395		5	Jakhu tank near Ropeway	added		05-12-20	Excellent
	2396		6	Public tap near Gaddi Khana	added		05-12-20	Excellent
	2397		7	Public tap near Chadha transport	added		05-12-20	Excellent
	2398		8	Public tap near Preet Hotel	added		05-12-20	Excellent
	2399		9	Public tap near Tibetan colony below bus stand	added	thermotolerant E.coli not detected	05-12-20	Suspicious
	2400		10	FinGASK TANK	added		05-12-20	Excellent
	2401	11	Ridge tank outlet	added		05-12-20	Excellent	
	2402	12	ADVANCE STUDY TANK	added		05-12-20	Excellent	
	2403	13	103 tank	added	thermotolerant E.coli not detected	05-12-20	satisfactory	
	2404	14	KLESTAN TANK	added		05-12-20	Excellent	
	2405	15	Gumma inlet	added		05-12-20	Excellent	
	2406	16	Giri inlet	added	thermotolerant E.coli not detected	05-12-20	satisfactory	
	2407	17	SANJAULI RESERVOIR	added		05-12-20	Excellent	
	2408	18	Dhali catchment	added		05-12-20	Excellent	

	2409		19	CHURAT JAGRATI INLET	added		05-12-20	Excellent
	2410		20	Dhali tank outlet	added	thermotolera nt E.coli not detected	05-12-20	satisfactory
05-10-20	2411	Samples received from A.E. , SJPN Ltd.	1	KASUMPATI RESERVOIR	added		13/5/2020	Excellent
	2412		2	PHASE III TANK NO 1	added		13/5/2020	Excellent
	2413		3	TARA MATA MANDIR TANK	added		13/5/2020	Excellent
	2414		4	PUBLIC TAP NEAR DHOBI GHAT ANNADALE	added		13/5/2020	Excellent
	2415		5	PUBLIC TAP NEAR LAXMI NIWAS	added		13/5/2020	Excellent
	2416		6	PUBLIC TAP NEAR BIHARI LAL COTTAGE ANNADALE	added		13/5/2020	Excellent
	2417		7	PUBLIC TAP NEAR KRISHNA HILL ANNADALE	added		13/5/2020	Excellent
	2418		8	MAINSFIELD TANK	added		13/5/2020	Excellent
	2419		9	JAKHU TANK NEAR ROPEWAY	added		13/5/2020	Excellent
	2420		10	TARA HALL TANK	added		13/5/2020	Excellent
	2421		11	PUBLIC TAP NBEAR LOWER SUMMER HILL CHOWK(REPEAT)	added		13/5/2020	Excellent
	2422		12	RIDGE TANK OUTLET	added		13/5/2020	Excellent
	2423		13	BHARARI TANK	added		13/5/2020	Excellent
	2424		14	GUMMA INLET	added		13/5/2020	Excellent
	2425		15	GIRI INLET	added		13/5/2020	Excellent
	2426		16	SANJAULI RESERVOIR	added		13/5/2020	Excellent
	2427		17	DHALLI CATCHMENT INLET	added		13/5/2020	Excellent
	2428		18	CHURAT AND JAGRITI INLET	added		13/5/2020	Excellent
	2429		19	DHALLI TANK OUTLET	added		13/5/2020	Excellent
	2430		20	KALYANI TANK CHARABRA	added		13/5/2020	Excellent
05-11-20	2431	Samples received from A.E. , SJPN Ltd.	1	KASUMPTI RESERVOIR	added		14/05/2020	Excellent
	2432		2	Phase III tank No. 1	added		14/05/2020	Excellent
	2433		3	TARA MATA MANDIR TANK	added		14/05/2020	Excellent
	2434		4	MAINSFIELD TANK	added		14/05/2020	Excellent

						thermotolera nt E.coli not detected		
	2435		5	Jakhu tank near Ropeway	added		14/05/2020	Satisfactory
	2436		6	Ridge tank outlet	added		14/05/2020	Excellent
	2437		7	Kamna devi tank	added		14/05/2020	Excellent
	2438		8	SUPPLY NEAR 18 FAMILY CPWD QUARTER BOILEUGANJ	added		14/05/2020	Excellent
	2439		9	BHIMAKALI TANK	added		14/05/2020	Excellent
	2440		10	CHAKKAR TANK	added		14/05/2020	Excellent
	2441		11	Public tap near Hari Mandir Chakar	added		14/05/2020	Excellent
	2442		12	103 tank	added		14/05/2020	Excellent
	2443		13	Tutikandi Tank	added		14/05/2020	Excellent
	2444		14	KLESTAN TANK	added		14/05/2020	Excellent
	2445		15	GUMMA INLET	added		14/05/2020	Excellent
	2446		16	GIRI INLET	added		14/05/2020	Excellent
	2447		17	SANJAULI RESERVOIR	added		14/05/2020	Excellent
	2448		18	DHALLI CATCHMENT INLET	added		14/05/2020	Excellent
	2449		19	CHURAT AND JAGRITI INLET	added		14/05/2020	Excellent
	2450		20	DHALLI TANK OUTLET	added		14/05/2020	Excellent
05-12-20	2451	Samples received from A.E. , SJPN Ltd.	1	KASUMPTI RESERVOIR	added		15/05/2020	Excellent
	2452		2	Phase III tank No. 1	added		15/05/2020	Excellent
	2453		3	TARA MATA MANDIR TANK	added		15/05/2020	Excellent
	2454		4	Jakhu Tank near Hanuman Temple	added		15/05/2020	Excellent
	2455		5	Ridge tank outlet	added		15/05/2020	Excellent
	2456		6	MAINSFIELD TANK	added		15/05/2020	Excellent
	2457		7	BANGALA COLONY TANK	added		15/05/2020	Excellent
	2458		8	PUBLIC TAP NEAR BANGALA COLONY	added		15/05/2020	Excellent
	2459		9	Public tap near MeHTA PARKING Engine ghar	added		15/05/2020	Excellent
	2460		10	ENGINE GHAR TANK	added		15/05/2020	Excellent
	2461		11	DHALLI CATCHMENT INLET	added		15/05/2020	Excellent
	2462		12	CHURAT AND JAGRITI INLET	added		15/05/2020	Excellent
	2463		13	DHALLI TANK OUTLET	added		15/05/2020	Excellent
	2464		14	BHARARI TANK	added		15/05/2020	Excellent
	2465		15	ADVANCE STUDY TANK	added		15/05/2020	Excellent

	2466		16	PHAGLI TANK	added		15/05/2020	Excellent
	2467		17	Public tap near Sanjauli chowk	added		15/05/2020	Excellent
	2468		18	SANJAULI RESERVOIR	added	thermotolerant E.coli not detected	15/05/2020	Satisfactory
	2469		19	Giri inlet	added		15/05/2020	Excellent
	2470		20	GuMMA INLET	added		15/05/2020	Excellent
13/5/2020	2471	Samples received from A.E. , SJPN Ltd.	1	KASUMPATI RESERVOIR	added		16/05/2020	Excellent
	2472		2	PHASE III TANK NO 1	added		16/05/2020	Excellent
	2473		3	TARA MATA MANDIR TANK	added		16/05/2020	Excellent
	2474		4	PUBLIC TAP NEAR MC OFFICE NEW SHIMLA	added		16/05/2020	Excellent
	2475		5	SECTOR 3 OLD TANK OUTLET	added		16/05/2020	Excellent
	2476		6	PUBLIC TAP NEAR KRANTI CHOWK	added		16/05/2020	Excellent
	2477		7	SECTOR 3 NEW TANK	added		16/05/2020	Excellent
	2478		8	PUBLIC TAP NEAR MANGLA BHAWAN	added		16/05/2020	Excellent
	2479		9	JAKHU TANK NEAR ROPEWAY	added		16/05/2020	Excellent
	2480		10	Ridge tank outlet	added		16/05/2020	Excellent
	2481		11	MAINSFIELD TANK	added		16/05/2020	Excellent
	2482		12	CHAKKAR TANK	added		16/05/2020	Excellent
	2483		13	103 TANK	added		16/05/2020	Excellent
	2484		14	KLESTAN TANK	added		16/05/2020	Excellent
	2485		15	DHALLI CATCHMENT INLET	added	thermotolerant E.coli not detected	16/05/2020	Satisfactory
	2486		16	CHURAT AND JAGRITI INLET	added	thermotolerant E.coli not detected	16/05/2020	Satisfactory
	2487		17	DHALLI TANK OUTLET	added		16/05/2020	Excellent
	2488		18	SANJAULI RESERVOIR	added		16/05/2020	Excellent
	2489		19	GIRI inlet	added		16/05/2020	Excellent
	2490		20	GUmma inlet	added		16/05/2020	Excellent

14/05/2020	2491	Samples received from A.E. , SJPN Ltd.	1	SAKRALA TANK	added		17/5/2020	Excellent
	2492		2	KASUMPTI RESERVOIR	added		17/5/2020	Excellent
	2493		3	S.D.A. KASUMPATI TANK	added		17/5/2020	Excellent
	2494		4	Public tap near Durga cottage S.D.A.	added		17/5/2020	Excellent
	2495		5	Phase III tank No. 1	added		17/5/2020	Excellent
	2496		6	TARA MATA MANDIR TANK	added		17/5/2020	Excellent
	2497		7	Public tap near Apna Medical store Chotta Shimla	added		17/5/2020	Excellent
	2498		8	PUBLIC TAP NEAR SERVANT QUARTERS KNOLLS WOOD	added		17/5/2020	Excellent
	2499		9	MAINSFIELD TANK	added		17/5/2020	Excellent
	2500		10	Jakhu tank Near Ropeway	added		17/5/2020	Excellent
	2501		11	RIDGE TANK OUTLET	added		17/5/2020	Excellent
	2502		12	BHIMAKALI TANK	added		17/5/2020	Excellent
	2503	13	Tutikandi tank	added	thermotolera nt E.coli not detected	17/5/2020	Unsatisfactory	
	2504	14	BHARARI TANK	added		17/5/2020	Excellent	
	2505	15	SANJAULI RESERVOIR	added		17/5/2020	Excellent	
	2506	16	GIRI INLET	added		17/5/2020	Excellent	
	2507	17	GUMMA INLET	added		17/5/2020	Excellent	
	2508	18	Dhalli catchment inlet	added		17/5/2020	Excellent	
	2509	19	Churat and Jagrati inlet	added		17/5/2020	Excellent	
	2510	20	Dhalli tank outlet	added		17/5/2020	Excellent	
15/05/2020	2511	Samples received from A.E. , SJPN Ltd.	1	KASUMPTI RESERVOIR	added		18/5/2020	Excellent
	2512		2	Phase III tank No. 1	added		18/5/2020	Excellent
	2513		3	TARA MATA MANDIR TANK	added		18/5/2020	Excellent
	2514		4	MAINSFIELD TANK	added		18/5/2020	Excellent
	2515		5	Jakhu tank Near Ropeway	added		18/5/2020	Excellent
	2516		6	RIDGE TANK OUTLET	added		18/5/2020	Excellent
	2517		7	SUPPLY NEAR BHALLA NIWAS BHARARI	added		18/5/2020	Excellent
	2518		8	PUBLIC TAP NEAR POLICE COLONY BHARARI	added		18/5/2020	Excellent

	2519		9	PUBLIC TAP NEAR BHARARI TEMPLE	added		18/5/2020	Excellent
	2520		10	PUBLIC TAP NEAR POLICE GROUND BHARARI	added		18/5/2020	Excellent
	2521		11	BHARARI TANK	added		18/5/2020	Excellent
	2522		12	KLESTAN TANK	added		18/5/2020	Excellent
	2523		13	ADVANCE STUDY TANK	added		18/5/2020	Excellent
	2524		14	PHAGLI TANK	added		18/5/2020	Excellent
	2525		15	SANJAULI RESERVOIR	added		18/5/2020	Excellent
	2526		16	GIRI INLET	added		18/5/2020	Excellent
	2527		17	GUMMA INLET	added		18/5/2020	Excellent
	2528		18	Dhali catchment inlet	added		18/5/2020	Excellent
	2529		19	Churat and Jagrati inlet	added		18/5/2020	Excellent
	2530		20	Dhali tank outlet	added		18/5/2020	Excellent
16/05/2020	2531	Samples received from A.E. , SJPN Ltd.	1	KASUMPTI RESERVOIR	added		19/05/2020	Excellent
	2532		2	Phase III tank No. 1	added		19/05/2020	Excellent
	2533		3	TARA MATA MANDIR TANK	added		19/05/2020	Excellent
	2534		4	Public tap near Tibetan colony below bus stand	added		19/05/2020	Excellent
	2535		5	Public tap near New Green Rajput Dhaba Shahi theater	added		19/05/2020	Excellent
	2536		6	Public tap near Eva Sale corp. Ganj bazar	added		19/05/2020	Excellent
	2537		7	PUBLIC TAP NEAR PURUSHARTHI BASTI	added		19/05/2020	Excellent
	2538		8	PUBLIC TAP NEAR INDIRA CHOWK LOWER BAZAR	added		19/05/2020	Excellent
	2539		9	Ridge tank outlet	added		19/05/2020	Excellent
	2540		10	MAINSFIELD TANK	added		19/05/2020	Excellent
	2541		11	Jakhu tank near Ropeway	added		19/05/2020	Excellent
	2542		12	CHAKKAR TANK	added		19/05/2020	Excellent
	2543		13	103 TANK	added		19/05/2020	Excellent
	2544		14	BHARARI TANK	added		19/05/2020	Excellent
	2545		15	SANJAULI RESERVOIR	added		19/05/2020	Excellent
	2546		16	GIRI INLET	added	thermotolera nt E.coli not detected	19/05/2020	satisfactory

	2547		17	GUMMA INLET	added	thermotolerant E.coli not detected	19/05/2020	Satisfactory
	2548		18	Dhali catchment inlet	added		19/05/2020	Excellent
	2549		19	Churat and Jagrati inlet	added		19/05/2020	Excellent
	2550		20	Dhali tank outlet	added		19/05/2020	Excellent
17/5/2020	2551	Samples received from A.E. , SJPN Ltd.	1	KASUMPTI RESERVOIR	added		20/05/2020	Excellent
	2552		2	PHASE III TANK NO.1	added		20/05/2020	Excellent
	2553		3	TARA MATA MANDIR TANK	added		20/05/2020	Excellent
	2554		4	JAKHOO TANK, NEAR ROPEWAY	added		20/05/2020	Excellent
	2555		5	RIDGE TANK OUTLET	added		20/05/2020	Excellent
	2556		6	MAINSFIELD TANK	added		20/05/2020	Excellent
	2557		7	P.TAP NEAR KALI KOTHI, TUTTIKANDI	added		20/05/2020	Excellent
	2558		8	P.TAP NEAR GOVT. SCHOOL PHAGLI	added		20/05/2020	Excellent
	2559		9	PHAGLI TANK	added		20/05/2020	Excellent
	2560		10	P.TAP NEAR TIBETAN COLONY, NABHA.	added	thermotolerant E.coli not detected	20/05/2020	Satisfactory
	2561		11	103 TANK	added		20/05/2020	Excellent
	2562		12	TUTIKANDI TANK	added	thermotolerant E.coli not detected	20/05/2020	Satisfactory
	2563		13	BHIMAKALI TANK	added	thermotolerant E.coli not detected	20/05/2020	Suspicious
	2564		14	GUMMA INLET	added		20/05/2020	Excellent
	2565		15	GIRI INLET	added		20/05/2020	Excellent
	2566		16	SANJAULI RESERVOIR	added		20/05/2020	Excellent
	2567		17	DHALLI CATCHMENT INLET	added		20/05/2020	Excellent
	2568		18	CHURAT & JAGROTI INLET	added		20/05/2020	Excellent
	2569		19	DHALLI TANK OUTLET	added		20/05/2020	Excellent
	2570		20	KALYANI TANK CHARABRA	added		20/05/2020	Excellent

18/5/2020	2571	Samples received from A.E. , SJPN Ltd.	1	KASUMPATI RESERVOIR	added		21/052020	Excellent
	2572		2	PHASE III TANK NO.1	added	thermotolerant E.coli not detected	21/052020	Satisfactory
	2573		3	TARA MATA MANDIR TANK	added		21/052020	Excellent
	2574		4	JAKHU TANK NEAR ROPEWAY	added		21/052020	Excellent
	2575		5	RIDGE TANK OUTLET	added	thermotolerant E.coli not detected	21/052020	Satisfactory
	2576		6	MAINSFIELD TANK	added		21/052020	Excellent
	2577		7	SUPPLY NEAR MC OFFICE CHAURA MAIDAN	added		21/052020	Excellent
	2578		8	PUBLIC TAP NEAR SUMMER HILL CHOWK	added		21/052020	Excellent
	2579		9	ADVANCE STUDY TANK	added	thermotolerant E.coli not detected	21/052020	Satisfactory
	2580		10	PUBLIC TAP NEAR RAJ DAIRY SUMMER HILL	added		21/052020	Excellent
	2581		11	SUMMER HILL BAJAR TANK	added		21/052020	Excellent
	2582		12	PUBLIC TAP NEAR LOWER SUMMER HILL	added		21/052020	Excellent
	2583		13	TUTIKHANDI TANK	added		21/052020	Excellent
	2584		14	KLESTAN TANK	added		21/052020	Excellent
	2585		15	SANJAULI RESERVOIR	added		21/052020	Excellent
	2586		16	GIRI inlet	added		21/052020	Excellent
	2587		17	GUMMA INLET	added		21/052020	Excellent
	2588		18	DHALLI CATCHMENT INLET	added	thermotolerant E.coli not detected	21/052020	Satisfactory
	2589		19	CHURAT AND JAGRITI INLET	added		21/052020	Excellent
	2590		20	DHALLI TANK OUTLET	added		21/052020	Excellent

19/05/2020	2591	Samples received from A.E. , SJPN Ltd.	1	KASUMPTI RESERVOIR	added		22/05/2020	Excellent
	2592		2	PHASE III TANK NO.1	added		22/05/2020	Excellent
	2593		3	TARA MATA MANDIR TANK	added		22/05/2020	Excellent
	2594		4	Jakhu Tank near Ropeway	added		22/05/2020	Excellent
	2595		5	RIDGE TANK OUTLET	added		22/05/2020	Excellent
	2596		6	MAINSFIELD TANK	added		22/05/2020	Excellent
	2597		7	CHAKKAR TANK	added		22/05/2020	Excellent
	2598		8	103 TANK	added		22/05/2020	Excellent
	2599		9	BHARARI TANK	added		22/05/2020	Excellent
	2600		10	SANJAULI RESERVOIR	added		22/05/2020	Excellent
	2601		11	GUMMA INLET	added		22/05/2020	Excellent
	2602		12	GIRI INLET	added		22/05/2020	Excellent
	2603		13	NORTH OAK UG TANK	added		22/05/2020	Excellent
	2604		14	Housing Board colony tank No.-1	added		22/05/2020	Excellent
	2605		15	Housing Board colony tank No.-2	added		22/05/2020	Excellent
	2606		16	PUBLIC TAP NEAR OLD POLICE THANA SANJAULI	added		22/05/2020	Excellent
	2607		17	Public tap near Luxmi Narayan temple sanjauli	added	thermotolerant E.coli not detected	22/05/2020	Satisfactory
	2608		18	DHALLI CATCHMENT INLET	added		22/05/2020	Excellent
	2609		19	CHURAT AND JAGRITI INLET	added		22/05/2020	Excellent
	2610		20	DHALLI TANK OUTLET	added	thermotolerant E.coli not detected	22/05/2020	Satisfactory