

DATED	LAB S.No.	RECEIVED FROM	DAILY S.No.	333	SODIUM THIOSULPHATE	FINAL REPORT (AFTER 72 HOURS)	FINAL REPORTING DATE	RESULT	
29/06/2020	3411	Samples received from A.E. , SJPN Ltd.	1	KASUMPATI RESERVOIR	added		07-02-20	Excellent	
			2	PHASE 3 TANK NO 1	added		07-02-20	Excellent	
			3	TARA MATA MANDIR TANK	added			07-02-20	Excellent
			4	MAINSFIELD TANK	added		thermotolerant E.coli not detected	07-02-20	Satisfactory
			5	JAKHU TRANK NEAR ROPEWAY	added			07-02-20	Excellent
			6	RIDGE TANK OUTLET	added			07-02-20	Excellent
			7	103 TANK	added			07-02-20	Excellent
			8	BHIMAKALI TANK	added		thermotolerant E.coli not detected	07-02-20	Satisfactory
			9	PUBLIC TAP NEAR LOWER SUMMER HILL	added			07-02-20	Excellent
			10	PUBLIC TAP NEAR RAJ DAIRY SUMMER HILL	added			07-02-20	Excellent
			11	SUMMER HILL BAJAR TANK	added			07-02-20	Excellent
			12	PUBLIC TAP NEAR SUMMER HILL CHOWK	added			07-02-20	Excellent
			13	ADVANCE STUDY TANK	added			07-02-20	Excellent
			14	DHALLI CATCHMENT INLET	added			07-02-20	Excellent
			15	CHURAT AND JAGRITI INLET	added			07-02-20	Excellent
			16	DHALLI TANK OUTLET	added			07-02-20	Excellent
			17	SANJAULI RESERVOIR	added			07-02-20	Excellent
			18	GIRI INLET	added			07-02-20	Excellent
			19	GUMMA INLET	added			07-02-20	Excellent
				3430		20	PUBLIC TAP NEAR MC OFFICE SANJAULI	added	
30/06/2020	3431	Samples received from A.E. , SJPN Ltd.	1	KASUMPTI RESERVOIR	added		07-03-20	Excellent	
			2	Phase III tank No. 1	added		07-03-20	Excellent	
			3	TARA MATA MANDIR TANK	added		07-03-20	Excellent	
			4	MAINSFIELD TANK	added		07-03-20	Excellent	
			5	Jakhu tank near ropeway	added		07-03-20	Excellent	
			6	Public tap near Goel Apartment Dhingu	added			07-03-20	Excellent

	3437		7	DHINGU MANDIR TANK	added		07-03-20	Excellent
	3438		8	Dhali catchment inlet	added		07-03-20	Excellent
	3439		9	Churat and Jagrati inlet	added		07-03-20	Excellent
	3440		10	Dhali tank outlet	added		07-03-20	Excellent
	3441		11	Public tap near Luxmi Narayan temple sanjauli	added		07-03-20	Excellent
	3442		12	PUBLIC TAP NEAR OLD POLICE THANA SANJAULI	added		07-03-20	Excellent
	3443		13	NORTH OAK O.H. TANK	added		07-03-20	Excellent
	3444		14	SANJAULI RESERVOIR	added		07-03-20	Excellent
	3445		15	Gumma Inlet	added		07-03-20	Excellent
	3446		16	GIRI INLET	added		07-03-20	Excellent
	3447		17	KLESTAN TANK	added		07-03-20	Excellent
	3448		18	CHAKKAR TANK	added		07-03-20	Excellent
	3449		19	TUTIKANDI TANK	added		07-03-20	Excellent
	3450		20	RIDGE TANK OUTLET	added		07-03-20	Excellent
07-01-20	3451	Samples received from A.E. , SJPN Ltd.	1	KASUMPATI RESERVOIR	added		07-04-20	Excellent
	3452		2	PHASE 3 TANK NO 1	added		07-04-20	Excellent
	3453		3	PHASE 3 TANK NO 3	added		07-04-20	Excellent
	3454		4	TARA MATA MANDIR TANK	added		07-04-20	Excellent
	3455		5	SECTOR 1 TANK	added		07-04-20	Excellent
	3456		6	PUBLIC TAP NEAR MC OFFICE NEW SHIMLA	added		07-04-20	Excellent
	3457		7	SECTOR 2 TANK	added		07-04-20	Excellent
	3458		8	SECTOR 4 TANK	added		07-04-20	Excellent
	3459		9	MAINSFIELD TANK	added		07-04-20	Excellent
	3460		10	JAKHU TANK NEAR ROPEWAY	added		07-04-20	Excellent
	3461		11	Ridge tank outlet	added		07-04-20	Excellent
	3462		12	PHAGLI TANK	added	thermotolerant E.coli not detected	07-04-20	Satisfactory
	3463		13	BHIMAKALI TANK	added		07-04-20	Excellent
	3464		14	BHARARI TANK	added	thermotolerant E.coli not detected	07-04-20	SATISFACTORY
	3465		15	SANJAULI RESERVOIR	added		07-04-20	Excellent

	3466		16	Gumma Inlet	added		07-04-20	Excellent
	3467		17	GIRI INLET	added		07-04-20	Excellent
	3468		18	DHALLI CATCHMENT INLET	added		07-04-20	Excellent
	3469		19	CHURAT AND JAGRITI INLET	added		07-04-20	Excellent
	3470		20	DHALLI TANK OUTLET	added		07-04-20	Excellent
07-02-20	3471	Samples received from A.E. , SJPN Ltd.	1	KASUMPTI RESERVOIR	added		07-05-20	Excellent
	3472		2	Phase III tank No. 1	added		07-05-20	Excellent
	3473		3	TARA MATA MANDIR TANK	added		07-05-20	Excellent
	3474		4	PUBLIC TAP NEAR PANCHIATHA	added		07-05-20	Excellent
	3475		5	Supply near SooD BHAWAN	added		07-05-20	Excellent
	3476		6	PUBLIC TAP NEAR BYPASS ROAD KHALINI	added		07-05-20	Excellent
	3477		7	PUBLIC TAP NEAR KHALINI CHOWK	added		07-05-20	Excellent
	3478		8	KNOLLSWOOD TANK	added		07-05-20	Excellent
	3479		9	MAINSFIELD TANK	added		07-05-20	Excellent
	3480		10	Jakhu tank near Ropeway	added		07-05-20	Excellent
	3481		11	RIDGE TANK OUTLET	added		07-05-20	Excellent
	3482		12	ADVANCE STUDY TANK	added		07-05-20	Excellent
	3483		13	103 TANK	added	thermotolerant E.coli not detected	07-05-20	Unsatisfactory
	3484		14	KLESTAN TANK	added		07-05-20	Excellent
	3485		15	Dhalli catchment inlet	added		07-05-20	Excellent
	3486		16	Churat and Jagrati inlet	added		07-05-20	Excellent
	3487		17	Dhalli tank outlet	added		07-05-20	Excellent
	3488		18	SANJAULI RESERVOIR	added		07-05-20	Excellent
	3489		19	GI RI INLET	added		07-05-20	Excellent
	3490		20	GuMMA INLET	added		07-05-20	Excellent
07-03-20	3491	Samples received from A.E. , SJPN Ltd.	1	KASUMPATI RESERVOIR	added		07-06-20	Excellent
	3492		2	PHASE 3 TANK NO 1	added		07-06-20	Excellent
	3493		3	TARA MATA MANDIR TANK	added		07-06-20	Excellent
	3494		4	MAINSFIELD TANK	added		07-06-20	Excellent
	3495		5	Public tap near five bench	added		07-06-20	Excellent
	3496		6	Public tap near Dhaulpur house Jakhu	added		07-06-20	Excellent
	3497		7	JAKHU TANK NEAR ROPEWAY	added		07-06-20	Excellent
	3498		8	JAKHU TANK NEAR HANuman Temple	added		07-06-20	Excellent
	3499		9	RIDGE TANK OUTLET	added		07-06-20	Excellent
	3500		10	SUPPLY NEAR HOLLY LODGE	added		07-06-20	Excellent

	3501		11	Public tap near Charlie mount	added		07-06-20	Excellent
	3502		12	CHAKKAR TANK	added		07-06-20	Excellent
	3503		13	TUTIKANDI TANK	added		07-06-20	Excellent
	3504		14	BHARARI TANK	added		07-06-20	Excellent
	3505		15	SANJAULI RESERVOIR	added		07-06-20	Excellent
	3506		16	GIRI INLET	added		07-06-20	Excellent
	3507		17	GUMMA INLET	added		07-06-20	Excellent
	3508		18	DHALLI TANK OUTLET	added		07-06-20	Excellent
	3509		19	CHURAT AND JAGRITI INLET	added		07-06-20	Excellent
	3510		20	DHALLI CATCHMENT INLET	added		07-06-20	Excellent
07-04-20	3511	Samples received from A.E. , SJPN Ltd.	1	KASUMPTI RESERVOIR	added		07-07-20	Excellent
	3512		2	MAINSFIELD TANK	added		07-07-20	Excellent
	3513		3	JAKHU TANK NEAR ROPEWAY	added		07-07-20	Excellent
	3514		4	BHIMAKALI TANK	added	thermotolerant E.coli not detected	07-07-20	SATISFACTORY
	3515		5	P.TAP NEAR VEDYA NIWAS	added		07-07-20	Excellent
	3516		6	P.TAP NEAR GUPTA PAN HOUSE TOTU	added		07-07-20	Excellent
	3517		7	P.TAP NEAR TOTU CHOWK	added		07-07-20	Excellent
	3518		8	P.TAP NEAR SHERU DHABA YADGAR	added	thermotolerant E.coli not detected	07-07-20	SATISFACTORY
	3519		9	YADGAR TANK	added		07-07-20	Excellent
	3520		10	P.TAP NEAR HARI MANDIR, CHAKKAR	added		07-07-20	Excellent
	3521		11	P. TAP NEAR HARI PALACE GHORACHOWKI	added		07-07-20	Excellent
	3522		12	PHAGLI TANK	added		07-07-20	Excellent
	3523		13	P.TAP NEAR COUNCILLOR HOUSE RULDABHATTA	added		07-07-20	Excellent
	3524		14	P.TAP NEAR BHAGWATI NIWAS LAKKAR BAZAAR	added		07-07-20	Excellent
	3525		15	RIDGE TANK OUTLET	added		07-07-20	Excellent
	3526		16	DHALLI TANK OUTLET	added		07-07-20	Excellent
	3527		17	DHALLI CATCHMENT INLET	added		07-07-20	Excellent
	3528		18	CHURAT & JAGROTI INLET	added		07-07-20	Excellent
	3529		19	SANJAULI RESERVOIR	added		07-07-20	Excellent
	3530		20	GUMMA INLET	added		07-07-20	Excellent
07-05-20	3531	Samples received from A.E. , SJPN Ltd.	1	KASUMPTI RESERVOIR	added		07-08-20	Excellent

	3532		2	PHASE III TANK NO. 1	added		07-08-20	Excellent
	3533		3	TARA MATA MANDIR TANK	added		07-08-20	Excellent
	3534		4	MAINSFIELD TANK	added		07-08-20	Excellent
	3535		5	JAKHU TANK NEAR ROPEWAY	added		07-08-20	Excellent
	3536		6	P.TAP NEAR GADDI KHANA	added		07-08-20	Excellent
	3537		7	P.TAP NEAR CHADHA TRANSPORT	added		07-08-20	Excellent
	3538		8	P.TAP NEAR PREET HOTEL	added		07-08-20	Excellent
	3539		9	P.TAP NEAR TIBETAN COLONY BELOW BUS STAND	added		07-08-20	Excellent
	3540		10	RIDGE TANK OUTLET	added		07-08-20	Excellent
	3541		11	P.TAP NEAR SUJILINE	added		07-08-20	Excellent
	3542		12	103 TANK	added		07-08-20	Excellent
	3543		13	ADVANCE STUDY TANK	added	thermotolerant E.coli not detected	07-08-20	SATISFACTORY
	3544		14	SANJAULI RESERVOIR	added	thermotolerant E.coli not detected	07-08-20	SATISFACTORY
	3545		15	GIRI INLET	added		07-08-20	Excellent
	3546		16	GUMMA INLET	added		07-08-20	Excellent
	3547		17	DHALLI CATCHMENT INLET	added	thermotolerant E.coli not detected	07-08-20	Unsatisfactory
	3548		18	CHURAT & JAGROTI INLET	added		07-08-20	Excellent
	3549		19	DHALLI TANK OUTLET	added		07-08-20	Excellent
	3550		20	KALYANI TANK CHARABRA	added		07-08-20	Excellent
07-06-20	3551	Samples received from A.E. , SJPN Ltd.	1	KASUMPATI RESERVOIR	added		07-09-20	Excellent
	3552		2	PHASE 3 TANK NO 1	added		07-09-20	Excellent
	3553		3	TARA MATA MANDIR TANK	added		07-09-20	Excellent
	3554		4	MAINSFIELD TANK	added		07-09-20	Excellent
	3555		5	JAKHU TANK NEAR ROPEWAY	added		07-09-20	Excellent
	3556		6	ADVANCE STUDY TANK	added		07-09-20	Excellent
	3557		7	PUBLIC TAP NEAR SUMMER HILL CHOWK	added		07-09-20	Excellent
	3558		8	PUBLIC TAP NEAR RAJ DAIRY	added		07-09-20	Excellent
	3559		9	SUMMER HILL Chowk tank	added		07-09-20	Excellent
	3560		10	PUBLIC TAP NEAR LOWER SUMMER HILL	added		07-09-20	Excellent
	3561		11	CHAKKAR TANK	added		07-09-20	Excellent
	3562		12	TUTIKANDI TANK	added		07-09-20	Excellent

	3563		13	RIDGE TANK OUTLET	added	thermotolerant E.coli not detected	07-09-20	SATISFACTORY
	3564		14	BHARARI TANK	added	thermotolerant E.coli not detected	07-09-20	SATISFACTORY
	3565		15	DHALLI TANK OUTLET	added		07-09-20	Excellent
	3566		16	CHURAT AND JAGRITI INLET	added	thermotolerant E.coli not detected	07-09-20	SATISFACTORY
	3567		17	DHALLI CATCHMENT INLET	added		07-09-20	Excellent
	3568		18	SANJAULI RESERVOIR	added		07-09-20	Excellent
	3569		19	GIRI INLET	added		07-09-20	Excellent
	3570		20	GUMMA INLET	added		07-09-20	Excellent
07-07-20	3571	Samples received from A.E. , SJPN Ltd.	1	KASUMPTI RESERVOIR	added	thermotolerant E.coli not detected	07-10-20	Suspicious
	3572		2	PHASE III TANK NO.1	added	thermotolerant E.coli not detected	07-10-20	Suspicious
	3573		3	TARA MATA MANDIR TANK	added	thermotolerant E.coli not detected	07-10-20	Satisfactory
	3574		4	MAINSFIELD TANK	added	thermotolerant E.coli not detected	07-10-20	satisfactory
	3575		5	JAKHU TANK NEAR ROPEWAY	added	thermotolerant E.coli not detected	07-10-20	Suspicious
	3576		6	DHALLI CATCHMENT INLET	added		07-10-20	Excellent
	3577		7	CHURAT & JAGROTI INLET	added	thermotolerant E.coli not detected	07-10-20	Suspicious
	3578		8	DHALLI TANK OUTLET	added	thermotolerant E.coli not detected	07-10-20	satisfactory
	3579		9	BANGALA COLONY TANK	added		07-10-20	Excellent
	3580		10	P.TAP NEAR BANGALA COLONY	added	thermotolerant E.coli not detected	07-10-20	satisfactory
	3581		11	P.TAP NEAR MEHTA PARKING, ENGINE GHAR	added	thermotolerant E.coli not detected	07-10-20	Unsatisfactory

	3582		12	ENGINE GHAR TANK	added	thermotolerant E.coli not detected	07-10-20	Suspicious
	3583		13	KLESTAN TANK	added	thermotolerant E.coli not detected	07-10-20	Unsatisfactory
	3584		14	BHIMAKALI TANK	added	thermotolerant E.coli not detected	07-10-20	satisfactory
	3585		15	PHAGLI TANK	added		07-10-20	Excellent
	3586		16	RIDGE TANK OUTLET	added	thermotolerant E.coli not detected	07-10-20	satisfactory
	3587		17	SANJAULI RESERVOIR	added	thermotolerant E.coli not detected	07-10-20	Suspicious
	3588		18	GI RI INLET	added		07-10-20	Excellent
	3589		19	GU MMA INLET	added		07-10-20	Excellent
	3590		20	P.TAP NEAR SANJAULI CHOWK	added		07-10-20	Excellent
07-08-20	3591	Samples received from A.E. , SJPN Ltd.	1	KASUMPATI RESERVOIR	added		07-11-20	Excellent
	3592		2	PHASE 3 TANK NO 1	added		07-11-20	Excellent
	3593		3	TARA MATA MANDIR TANK	added	thermotolerant E.coli not detected	07-11-20	satisfactory
	3594		4	PUBLIC TAP NEAR MC OFFICE NEW SHIMLA	added		07-11-20	Excellent
	3595		5	SECTOR 3 OLD TANK	added	thermotolerant E.coli not detected	07-11-20	satisfactory
	3596		6	PUBLIC TAP NEAR KRANTI CHOWK	added	thermotolerant E.coli not detected	07-11-20	satisfactory
	3597		7	SECTOR 3 NEW TANK	added	thermotolerant E.coli not detected	07-11-20	satisfactory
	3598		8	PUBLIC TAP NEAR MANGLA BHAWAN	added	thermotolerant E.coli not detected	07-11-20	satisfactory
	3599		9	MAINSFIELD TANK	added		07-11-20	Excellent

	3600		10	JAKHU TANK NEAR ROPEWAY	added	thermotolerant E.coli not detected	07-11-20	satisfactory
	3601		11	RIDGE TANK OUTLET	added		07-11-20	Excellent
	3602		12	ADVANCE STUDY TANK	added		07-11-20	Excellent
	3603		13	103 TANK	added		07-11-20	Excellent
	3604		14	BHARARI TANK	added		07-11-20	Excellent
	3605		15	DHALLI TANK OUTLET	added		07-11-20	Excellent
	3606		16	CHURAT AND JAGRITI INLET	added		07-11-20	Excellent
	3607		17	DHALLI CATCHMENT INLET	added	thermotolerant E.coli not detected	07-11-20	Unsatisfactory
	3608		18	SANJAULI RESERVOIR	added		07-11-20	Excellent
	3609		19	GIRI INLET	added		07-11-20	Excellent
	3610		20	GUMMA INLET	added		07-11-20	Excellent
07-09-20	3611	Samples received from A.E. , SJPN Ltd.	1	SAKRALA TANK	added		07-12-20	Excellent
	3612		2	KASUMPTI RESERVOIR	added	thermotolerant E.coli not detected	07-12-20	satisfactory
	3613		3	Public tap near A block Vikas nagar	added	thermotolerant E.coli not detected	07-12-20	satisfactory
	3614		4	SDA KASUMPTI TANK	added	thermotolerant E.coli not detected	07-12-20	Suspicious
	3615		5	Phase III tank No. 1	added	thermotolerant E.coli not detected	07-12-20	satisfactory
	3616		6	TARA MATA MANDIR TANK	added	thermotolerant E.coli not detected	07-12-20	Suspicious
	3617		7	MAINSFIELD TANK	added	thermotolerant E.coli not detected	07-12-20	satisfactory
	3618		8	JAKHU TANK NEAR ROPEWAY	added	thermotolerant E.coli not detected	07-12-20	satisfactory
	3619		9	Public tap near Police gumti Chotta Shimla	added		07-12-20	Excellent



	<b>3620</b>		10	PUBLIC TAP NEAR SERVANT QUARTERS KNOLLS WOOD	<b>added</b>	thermotolerant E.coli not detected	07-12-20	<b>satisfactory</b>
	<b>3621</b>		11	RIDGE TANK OUTLET	<b>added</b>		07-12-20	<b>Excellent</b>
	<b>3622</b>		12	TUTIKANDI TANK	<b>added</b>		07-12-20	<b>Excellent</b>
	<b>3623</b>		13	CHAKKAR TANK	<b>added</b>	thermotolerant E.coli not detected	07-12-20	<b>satisfactory</b>
	<b>3624</b>		14	KLESTAN TANK	<b>added</b>		07-12-20	<b>Excellent</b>
	<b>3625</b>		15	Dhalli tank outlet	<b>added</b>		07-12-20	<b>Excellent</b>
	<b>3626</b>		16	Churat and Jagrati inlet	<b>added</b>		07-12-20	<b>Excellent</b>
	<b>3627</b>		17	Dhalli catchment inlet	<b>added</b>		07-12-20	<b>Excellent</b>
	<b>3628</b>		18	GIRI INLET	<b>added</b>		07-12-20	<b>Excellent</b>
	<b>3629</b>		19	GUMMA INLET	<b>added</b>		07-12-20	<b>Excellent</b>
	<b>3630</b>		20	SANJAULI RESERVOIR	<b>added</b>		07-12-20	<b>Excellent</b>