

DATED	LAB S.No.	RECEIVED FROM	DAILY S.No.	333	SODIUM THIOSULPH ATE	FINAL REPORT (AFTER 72 HOURS)	FINAL REPORTING DATE	RESULT
	4331		20	Public tap near UCO bank Dhalli	added	thermotolerant E.coli	16/08/2020	SATISFACTORY
14/08/2020	4332	Samples received from A.	1	KASUMPATI RESERVOIR	added		17/08/2020	Excellent
	4333		2	PHASE 3 TANK NO 1	added	THERMOTOLERANT E.COLI NOT DETECTED	17/08/2020	SUSPICIOUS
	4334		3	TARA MATA MANDIR TANK	added		17/08/2020	Excellent
	4335		4	MAINSFIELD TANK	added		17/08/2020	Excellent
	4336		5	JAkhu tank near HAnuman Temple	added		17/08/2020	Excellent
	4337		6	RIDGE TANK OUTLET	added	THERMOTOLERANT E.COLI NOT DETECTED	17/08/2020	SUSPICIOUS
	4338		7	ADVANCE STUDY TANK	added		17/08/2020	Excellent
	4339		8	PUBLIC TAP NEAR SUMMER HILL CHOWK	added		17/08/2020	Excellent
	4340		9	PUBLIC TAP NEAR RAJ DAIRY SUMMER HILL	added		17/08/2020	Excellent
	4341		10	SUMMER HILL BAJAR TANK	added		17/08/2020	Excellent
	4342		11	PUBLIC TAP NEAR LOWER SUMMER HILL	added		17/08/2020	Excellent
	4343		12	BHIMAKALI TANK	added		17/08/2020	Excellent
	4344		13	TUTIKANDI TANK	added		17/08/2020	Excellent
	4345		14	KLESTON TANK	added		17/08/2020	Excellent
	4346		15	SANJAULI RESERVOIR	added		17/08/2020	Excellent
	4347		16	GiRI INLET	added	thermotolerant E.coli not detected	17/08/2020	SATISFACTORY
	4348		17	GuMMA INLET	added		17/08/2020	Excellent
	4349		18	DHALLI CATCHMENT INLET	added		17/08/2020	Excellent
	4350		19	CHURAT AND JAGRITI INLET	added	thermotolerant E.coli not detected	17/08/2020	SATISFACTORY
	4351		20	DHALLI TANK OUTLET	added		17/08/2020	Excellent
15/08/2020	4352	Samples received from A.	1	KASUMPATI RESERVOIR	added		18/08/2020	Excellent
	4353		2	MAINSFIELD TANK	added		18/08/2020	Excellent
	4354		3	JAKHU TANK NEAR HANUMAN TEMPLE	added	thermotolerant E.coli not detected	18/08/2020	SaTISFACTORY
	4355		4	103 TANK	added		18/08/2020	Excellent
	4356		5	CHAKKAR TANK	added		18/08/2020	Excellent
	4357		6	RIDGE TANK OUTLET	added		18/08/2020	Excellent
	4358		7	ENGINE GHAR TANK	added		18/08/2020	Excellent

	4359		8	BANGALA COLONY TANK	added		18/08/2020	Excellent
	4360		9	SANJAULI RESERVOIR	added		18/08/2020	Excellent
	4361		10	GIRI INLET	added		18/08/2020	Excellent
	4362		11	GuMMA INLET	added		18/08/2020	Excellent
	4363		12	NORTH OAK UG TANK	added	thermotolerant E.coli not detected	18/08/2020	SaTISFACTORY
	4364		13	NORTH OAK O.H. TANK	added		18/08/2020	Excellent
	4365		14	P.TAP NEAR SANJAULI CHOWK	added		18/08/2020	Excellent
	4366		15	P.TAP NEAR OLD POLICE THANA SANJAULI	added		18/08/2020	Excellent
	4367		16	P.TAP NEAR LAXMI NARAYAN TEMPLE	added		18/08/2020	Excellent
	4368		17	P.TAP UCO BANK DHALLI	added		18/08/2020	Excellent
	4369		18	DHALLI CATCHMENT INLET	added		18/08/2020	Excellent
	4370		19	CHURAT AND JAGRATI INLET	added		18/08/2020	Excellent
	4371		20	DHALLI TANK OULET	added		18/08/2020	Excellent
16/08/2020	4372	Samples received from A.	1	KASUMPTI RESERVOIR	added		19/08/2020	Excellent
	4373		2	Phase III tank No. 1	added		19/08/2020	Excellent
	4374		3	Tara mata mandir tank	added		19/08/2020	Excellent
	4375		4	PUBLIC TAP NEAR MC OFFICE NEW SHIMLA	added	Thermotolerant E.coli not detected	19/08/2020	SATISFACTORY
	4376		5	Sector-3 old tank outlet	added		19/08/2020	Excellent
	4377		6	PUBLIC TAP NEAR KRANTI CHOWK	added		19/08/2020	Excellent
	4378		7	Sector-3 new tank	added		19/08/2020	Excellent
	4379		8	Public tap near Mangla bhawan	added		19/08/2020	Excellent
	4380		9	MAINSFIELD TANK	added		19/08/2020	Excellent
	4381		10	Jakhu tank near Hanuman temple	added		19/08/2020	Excellent
	4382		11	RIDGE TANK OUTLET	added		19/08/2020	Excellent
	4383		12	TUTIKANDI TANK	added		19/08/2020	Excellent
	4384		13	BHARARI TANK	added		19/08/2020	Excellent
	4385		14	SANJAULI RESERVOIR	added		19/08/2020	Excellent
	4386		15	GUMMA INLET	added	THERMOTOLERANT E.COLI NOT DETECTED	19/08/2020	SaTISFACTORY
	4387		16	GIRI INLET	added		19/08/2020	Excellent
	4388		17	Dhalli catchment inlet	added		19/08/2020	Excellent
	4389		18	Churat and Jagrati inlet	added		19/08/2020	Excellent
	4390		19	Dhalli tank outlet	added		19/08/2020	Excellent
	4391		20	KALYANI TANK CHARABRA	added		19/08/2020	Excellent

17/08/2020	4392	Samples received from A.	1	KASUMPATI RESERVOIR	added		20/08/2020	Excellent
	4393		2	SAKRALA TANK	added		20/08/2020	Excellent
	4394		3	P.TAP NEAR APNA MEDICAL STORE CHOTTA SHIMLA	added		20/08/2020	Excellent
	4395		4	P.TAP NEAR POLICE GUMTI CHOTTA SHIMLA	added		20/08/2020	Excellent
	4396		5	P.TAP NEAR SERVANT QUARTER	added		20/08/2020	Excellent
	4397		6	KNOLLSWOOD TANK	added		20/08/2020	Excellent
	4398		7	MAINSFIELD TANK	added		20/08/2020	Excellent
	4399		8	JAKHU TANK NEAR HANUMAN TEMPLE	added		20/08/2020	Excellent
	4400		9	RIDGE TANK OUTLET	added		20/08/2020	Excellent
	4401		10	PHAGLI TANK	added		20/08/2020	Excellent
	4402		11	CHAKKAR TANK	added	thermotolerant E.coli not detected	20/08/2020	SATISFACTORY
	4403		12	KLESTON TANK	added	thermotolerant E.coli not detected	20/08/2020	SaTISFACTORY
	4404		13	BHARARI TANK	added		20/08/2020	Excellent
	4405		14	SANJALI RESERVOIR	added		20/08/2020	Excellent
	4406		15	GI RI INLET	added		20/08/2020	Excellent
	4407		16	GUMMA INLET	added		20/08/2020	Excellent
	4408		17	DHALLI CATCHMENT INLET	added		20/08/2020	Excellent
	4409		18	CHURAT AND JAGROTI INLET	added		20/08/2020	Excellent
	4410		19	DHALLI TANK OUTLET	added		20/08/2020	Excellent
	4411		20	P.TAP NEAR UCO BANK DHALLI	added		20/08/2020	Excellent
18/08/2020	4412	Samples received from A.	1	KASUMPATI RESERVOIR	added		21/08/2020	Excellent
	4413		2	MAINSFIELD TANK	added		21/08/2020	Excellent
	4414		3	Jakhu tank near Hanuman temple	added		21/08/2020	Excellent
	4415		4	103 tank	added		21/08/2020	Excellent
	4416		5	BHIMAKALI TANK	added		21/08/2020	Excellent
	4417		6	RIDGE TANK OUTLET	added		21/08/2020	Excellent
	4418		7	PUBLIC TAP NEAR POLICE GROUND BHARARI	added		21/08/2020	Excellent
	4419		8	PUBLIC TAP NEAR BHARARI TEMPLE	added		21/08/2020	Excellent
	4420		9	Public tap near Bhalla niwas Bharari	added	Thermotolerant E.coli not detected	21/08/2020	SATISFACTORY
	4421		10	PUBLIC TAP NEAR POLICE COLONY BHARARI	added		21/08/2020	Excellent

