

| DATED | LAB S.No. | RECEIVED FROM | DAILY S.No. | 333 E | SODIUM THIOSULPHAT | FINAL REPORT (AFTER 72 HOURS) | FINAL REPORTING DATE | RESULT |
|------------|-----------|---|-------------|--|--------------------|------------------------------------|----------------------|--------------|
| 31/08/2020 | 4672 | Samples received from A.E. , SJPN Ltd. | 1 | KASUMPTI RESERVOIR | added | | 09-03-20 | Excellent |
| | 4673 | | 2 | PHASE III TANK NO. 1 | added | | 09-03-20 | Excellent |
| | 4674 | | 3 | TARA MATA MANDIR | added | | 09-03-20 | Excellent |
| | 4675 | | 4 | SECT-3 OLD TANK OUTLET | added | | 09-03-20 | Excellent |
| | 4676 | | 5 | P.TAP NEAR KRANTI CHOWK | added | thermotolerant E.coli not detected | 09-03-20 | sATISFACTORY |
| | 4677 | | 6 | SECTOR 3 NEW TANK | added | | 09-03-20 | Excellent |
| | 4678 | | 7 | P.TAP NEAR MANGLA BHAWAN, NEW SHIMLA | added | | 09-03-20 | Excellent |
| | 4679 | | 8 | P.TAP NEAR EVA SALE CORP, GUNJ BAZAAR | added | | 09-03-20 | Excellent |
| | 4680 | | 9 | P.TAP NEAR SUBZI MANDI (REPEAT) | added | | 09-03-20 | Excellent |
| | 4681 | | 10 | P.TAP NEAR INDIRA CHOWK (REPEAT) | added | | 09-03-20 | Excellent |
| | 4682 | | 11 | RIDGE TANK OUTLET | added | thermotolerant E.coli not detected | 09-03-20 | SATISFACTORY |
| | 4683 | | 12 | CHAKKAR TANK | added | | 09-03-20 | Excellent |
| | 4684 | | 13 | PHAGLI TANK | added | Thermotolerant E.coli not detected | 09-03-20 | SATISFACTORY |
| | 4685 | | 14 | BHARARI TANK | added | Thermotolerant E.coli not detected | 09-03-20 | SATISFACTORY |
| | 4686 | | 15 | SANJAULI RESERVOIR | added | | 09-03-20 | Excellent |
| | 4687 | | 16 | GI RI INLET | added | | 09-03-20 | Excellent |
| | 4688 | | 17 | GU MMA INLET | added | | 09-03-20 | Excellent |
| | 4689 | | 18 | DHALLI CATCHMENT INLET | added | | 09-03-20 | Excellent |
| | 4690 | | 19 | CHURAT & JAGROTI INLET | added | | 09-03-20 | Excellent |
| | 4691 | | 20 | DHALLI TANK OUTLET | added | THERMOTOLERANT E.COLI NOT DETECTED | 09-03-20 | sATISFACTORY |
| 01-092020 | 4692 | Samples received from A.E. , SJPN Ltd. | 1 | KASUMPTI RESERVOIR | added | | 09-04-20 | Excellent |
| | 4693 | | 2 | SAKRALA TANK | added | | 09-04-20 | Excellent |
| | 4694 | | 3 | PHASE III TANK NO. 1 | added | | 09-04-20 | Excellent |
| | 4695 | | 4 | P.TAP NEAR KALI MATAMANDIR, BHAGWATI NAGAR | added | | 09-04-20 | Excellent |
| | 4696 | | 5 | P.TAP NEAR PANCHATHA | added | | 09-04-20 | Excellent |
| | 4697 | | 6 | P.TAP NEAR LOWER KHALINI CHOWK | added | | 09-04-20 | Excellent |
| | 4698 | | 7 | P.TAP NEAR NEAR KHALINI CHOWK | added | | 09-04-20 | Excellent |
| | 4699 | | 8 | P.TAP NEAR SERVANT QUARTER , KNOLLSWOOD | added | | 09-04-20 | Excellent |
| | 4700 | | 9 | P.TAP NEAR POLICE GUMTI CHOTTA SHIMLA | added | | 09-04-20 | Excellent |

| | | | | | | | | |
|----------|------|---|----|---|-------|---------------------------------------|----------|----------------|
| | 4701 | | 10 | MAINSFIELD TANK | added | | 09-04-20 | Excellent |
| | 4702 | | 11 | JAHKOO TANK NEAR ROPEWAY | added | | 09-04-20 | Excellent |
| | 4703 | | 12 | RIDGE TANK OUTLET | added | | 09-04-20 | Excellent |
| | 4704 | | 13 | 103 TANK | added | | 09-04-20 | Excellent |
| | 4705 | | 14 | KLESTON TANK | added | | 09-04-20 | Excellent |
| | 4706 | | 15 | SANJAULI RESERVOIR | added | | 09-04-20 | Excellent |
| | 4707 | | 16 | GiRI INLET | added | | 09-04-20 | Excellent |
| | 4708 | | 17 | GUMMA INLET | added | | 09-04-20 | Excellent |
| | 4709 | | 18 | DHALLI CATCHMENT INLET | added | | 09-04-20 | Excellent |
| | 4710 | | 19 | CHURAT AND JAGROTI INLET | added | | 09-04-20 | Excellent |
| | 4711 | | 20 | DHALLI TANK OUTLET | added | | 09-04-20 | Excellent |
| 02-09-20 | 4712 | Samples received from A.E. , SJPN Ltd. | 1 | KASUMPATI RESERVOIR | added | | 09-05-20 | Excellent |
| | 4713 | | 2 | TARA MATA MANDIR TANK | added | | 09-05-20 | Excellent |
| | 4714 | | 3 | MAINSFIELD TANK | added | | 09-05-20 | Excellent |
| | 4715 | | 4 | JAKHU TANK NEAR HANUMAN TEMPLE | added | | 09-05-20 | Excellent |
| | 4716 | | 5 | PUBLIC TAP NEAR BHARARI TEMPLE | added | | 09-05-20 | Excellent |
| | 4717 | | 6 | PUBLIC TAP NEAR POLICE COLONY BHARARI | added | | 09-05-20 | Excellent |
| | 4718 | | 7 | SUPPLY NEAR BHalla niwas, LOWER BHARARI | added | | 09-05-20 | Excellent |
| | 4719 | | 8 | PUBLIC TAP NEAR POLICE GROUND BHARARI | added | | 09-05-20 | Excellent |
| | 4720 | | 9 | BHARARI TANK | added | | 09-05-20 | Excellent |
| | 4721 | | 10 | KLESTON TANK | added | thermotolerant E.coli not detected | 09-05-20 | sATISFACTORY |
| | 4722 | | 11 | TUTIKANDHI TANK | added | thermotolerant E.coli not detected | 09-05-20 | sATISFACTORY |
| | 4723 | | 12 | PUBLIC TANK NEAR TIBETIAN COLONY NABHA(REPEAT) | added | | 09-05-20 | Excellent |
| | 4724 | | 13 | ADVANCE STUDY TANK | added | | 09-05-20 | Excellent |
| | 4725 | | 14 | SANJAULI RESERVOIR | added | | 09-05-20 | Excellent |
| | 4726 | | 15 | GiRI INLET | added | thermotolerant E.coli not detected | 09-05-20 | sATISFACTORY |
| | 4727 | | 16 | GUMMA INLET | added | | 09-05-20 | Excellent |
| | 4728 | | 17 | Public tap near UCO bank Dhalli(REPEAT) | added | thermotolerant E.coli not detected | 09-05-20 | UNSATISFACTORY |
| | 4729 | | 18 | DHALLI CATCHMNT INLET | added | thermotolerant E.coli not detected | 09-05-20 | SUSPICIOUS |
| | 4730 | | 19 | CHURAT AND JAGRITI INLET | added | | 09-05-20 | Excellent |
| | 4731 | | 20 | DHALLI TANK OUTLET | added | thermotolerant E.coli not detected | 09-05-20 | SATISFACTORY |

| | | | | | | | | |
|----------|------|---|----|---|-------|------------------------------------|----------|----------------|
| 03-09-20 | 4732 | Samples received from A.E. , SJPN Ltd. | 1 | KASUMPTI RESERVOIR | added | | 09-06-20 | Excellent |
| | 4733 | | 2 | Phase III tank No. 1 | added | | 09-06-20 | Excellent |
| | 4734 | | 3 | MAINSFIELD TANK | added | | 09-06-20 | Excellent |
| | 4735 | | 4 | Jakhu tank near Hanuman Temple | added | | 09-06-20 | Excellent |
| | 4736 | | 5 | Public tap near EVA salesa Corporation Ganj bazar | added | | 09-06-20 | Excellent |
| | 4737 | | 6 | Public tap near Purasharathi basti | added | | 09-06-20 | Excellent |
| | 4738 | | 7 | Public tap near Khadi bhandar Mall road | added | | 09-06-20 | Excellent |
| | 4739 | | 8 | Public tap near Samsung shop Mall road | added | | 09-06-20 | Excellent |
| | 4740 | | 9 | PUBLIC TAP NEAR HPMC RIDGE | added | | 09-06-20 | Excellent |
| | 4741 | | 10 | RIDGE TANK OUTLET | added | | 09-06-20 | Excellent |
| | 4742 | | 11 | Fingask tank-1 | added | | 09-06-20 | Excellent |
| | 4743 | | 12 | Fingask tank-2 | added | Thermotolerant E.coli not detected | 09-06-20 | SATISFACTORY |
| | 4744 | | 13 | BHARARI TANK | added | | 09-06-20 | Excellent |
| | 4745 | | 14 | SANJAULI RESERVOIR | added | | 09-06-20 | Excellent |
| | 4746 | | 15 | GI RI INLET | added | | 09-06-20 | Excellent |
| | 4747 | | 16 | GuMMA INLET | added | | 09-06-20 | Excellent |
| | 4748 | | 17 | PUBLIC TAP NEAR DHALLI CHOWK | added | Thermotolerant E.coli not detected | 09-06-20 | UNSATISFACTORY |
| | 4749 | | 18 | Dhalli catchment inlet | added | | 09-06-20 | Excellent |
| | 4750 | | 19 | Churat and Jagrati inlet | added | | 09-06-20 | Excellent |
| | 4751 | | 20 | Dhalli tank outlet | added | | 09-06-20 | Excellent |
| 04-09-20 | 4752 | Samples received from A.E. , SJPN Ltd. | 1 | KASUMPTI RESERVOIR | added | | 09-07-20 | Excellent |
| | 4753 | | 2 | TARA MATA MANDIR TANK | added | | 09-07-20 | Excellent |
| | 4754 | | 3 | MAINSFIELD TANK | added | | 09-07-20 | Excellent |
| | 4755 | | 4 | JAKHU TANK NEAR HANUMAN TEMPLE | added | | 09-07-20 | SATISFACTORY |
| | 4756 | | 5 | SUPPLY NEAR SILVERTON ANNADALE | added | | 09-07-20 | Excellent |
| | 4757 | | 6 | SUPPLY NEAR GRACE VILLA, ANNADALE | added | | 09-07-20 | Excellent |
| | 4758 | | 7 | P.TAP NEAR KRISHNA HILL, ANNADALE | added | | 09-07-20 | Excellent |
| | 4759 | | 8 | P.TAP NEAR CHAMBA HOUSE, ANNADALE | added | | 09-07-20 | Excellent |
| | 4760 | | 9 | P.TAP NEAR LUXMI NIWAS | added | | 09-07-20 | Excellent |
| | 4761 | | 10 | P.TAP NEAR BIHARI LAL COTTAGE, ANNADALE | added | | 09-07-20 | Excellent |
| | 4762 | | 11 | P.TAP NEAR KALA SADAN, ANNADALE | added | | 09-07-20 | Excellent |
| | 4763 | | 12 | SUPPLY NEAR VALANCIA ESTATE, ANANDALE | added | | 09-07-20 | Excellent |
| | 4764 | | 13 | TARA HALL TANK | added | thermotolerant E.coli not detected | 09-07-20 | SATISFACTORY |
| | 4765 | | 14 | KLESTON TANK | added | | 09-07-20 | Excellent |
| | 4766 | | 15 | SANJAULI RESERVOIR | added | | 09-07-20 | Excellent |

| | | | | | | | | |
|----------|------|---|----|---------------------------------------|-------|------------------------------------|----------|----------------|
| | 4767 | | 16 | GiRI INLET | added | | 09-07-20 | Excellent |
| | 4768 | | 17 | GuMMA INLET | added | | 09-07-20 | Excellent |
| | 4769 | | 18 | DHALLI CATCHMENT INLET | added | | 09-07-20 | Excellent |
| | 4770 | | 19 | CHURAT & JAGROT I INLET | added | | 09-07-20 | Excellent |
| | 4771 | | 20 | DHALLI TANK OUTLET | added | | 09-07-20 | Excellent |
| 05-09-20 | 4772 | Samples received from A.E. , SJPN Ltd. | 1 | KASUMPATI RESERVOIR | added | | 09-08-20 | Excellent |
| | 4773 | | 2 | PHASE 3 TANK NO 1 | added | Thermotolerant E.coli not detected | 09-08-20 | SATISFACTORY |
| | 4774 | | 3 | MAINSFIELD TANK | added | | 09-08-20 | Excellent |
| | 4775 | | 4 | JAKHU TANK NEAR HANUMAN TEMPLE | added | | 09-08-20 | Excellent |
| | 4776 | | 5 | BHIMAKALI TANK | added | | 09-08-20 | Excellent |
| | 4777 | | 6 | PUBLIC TAP NEAR VIDYA NIWAS NEAR TOTU | added | thermotolerant E.coli not detected | 09-08-20 | SATISFACTORY |
| | 4778 | | 7 | PUBLIC TAP NEAR GUPTa pan house,TOTU | added | | 09-08-20 | Excellent |
| | 4779 | | 8 | PUBLIC TAP NEAR TOTU CHOWK | added | Thermotolerant E.coli not detected | 09-08-20 | SATISFACTORY |
| | 4780 | | 9 | PUBLIC TAP NEAR PNB TOTU | added | | 09-08-20 | Excellent |
| | 4781 | | 10 | PUBLIC TAP NEAR SHERU DHABHA TOTU | added | Thermotolerant E.coli not detected | 09-08-20 | SATISFACTORY |
| | 4782 | | 11 | YADGAR TANK | added | | 09-08-20 | Excellent |
| | 4783 | | 12 | PUBLIC TAP NEAR SBI ATM TOTU CHOWK | added | | 09-08-20 | Excellent |
| | 4784 | | 13 | CHAKKAR TANK | added | Thermotolerant E.coli not detected | 09-08-20 | SATISFACTORY |
| | 4785 | | 14 | BHARARI TANK | added | Thermotolerant E.coli not detected | 09-08-20 | SUSPICIOUS |
| | 4786 | | 15 | SANJAULI RESERVOIR | added | Thermotolerant E.coli not detected | 09-08-20 | SUSPICIOUS |
| | 4787 | | 16 | GiRI INLET | added | | 09-08-20 | Excellent |
| | 4788 | | 17 | GUMMA INLET | added | Thermotolerant E.coli not detected | 09-08-20 | SATISFACTORY |
| | 4789 | | 18 | DHALLI CATCHMENT INLET | added | | 09-08-20 | Excellent |
| | 4790 | | 19 | CHURAT AND JAGRITI INLET | added | Thermotolerant E.coli not detected | 09-08-20 | UNSATISFACTORY |
| | 4791 | | 20 | DHALLI TANK OUTLET | added | Thermotolerant E.coli not detected | 09-08-20 | SUSPICIOUS |